



C338 SOFTWARE RELEASE NOTES

1.72

C338 software update 1.72 is a maintenance release that includes the following changes:

Add indicators when the following faults occur

- Overheat – C2 is shown in the display while the standby LED flashes slowly in red
- DC error – C2 is shown in the display while the standby LED flashes rapidly in red

Software Details

Software details after automatic software update

- MCU : 1.72
- System firmware : 9624
- Cast firmware : 1.28