



C 338 SOFTWARE RELEASE NOTES

V 1.63

C 338 software update V 1.63 is a maintenance release that includes the following changes:

- If the automatic software update is interrupted, the unit will recover and the software update will resume after powering ON again.
- Resolves random incidences of no audio when C 338 wakes up from standby mode via playback of network connected Apps.
- The current Source will automatically switch to Wi-Fi/BT source when Wi-Fi setup connection is initiated via Google Home.
- Android devices' compatibility is greatly improved with Google Home Wi-Fi setup.

New Features

- BT connection can now be disconnected by pressing the remote control [▶] (PLAY) button until the BT/Wi-Fi icon blinks 3 times.