



D 1050 Software Release Notes

V3.1

The D 1050 software update V3.1 is a maintenance release that includes the following changes:

- Defeat relay click noise at USB source when playback is resumed from pause mode of more than 5 seconds.
- Change remote control code from AMP library code to DAC library code.
 - Applicable NAD remote controls for D1050 are those with the DAC library code like the DR1 or the HTR version remote controls wherein the DAC library can be programmed.
- Improved auto standby mode with SPDIF sources.