

## **C338 SOFTWARE RELEASE NOTES**

## V 1.65

C338 software update V 1.65 is a maintenance release that includes the following change:

• Spotify Connect playability issues are fixed.

## **New Feature**

- Bluetooth can be made discoverable or invisible. This can be done by
  - → Bluetooth ON (discoverable): Press and hold [▶] button of AMP3 remote control until BT/Wi-Fi display icon blinks thrice.
  - → Bluetooth OFF (invisible): Press and hold [▶] button of AMP3 remote control until BT/Wi-Fi display icon blinks twice.

**Note**: *Previous feature of disconnecting BT connection is not available anymore.* 

## **Software Details**

Software details after automatic software update

- MCU : 1.65
- System firmware : 9624
- Cast firmware : 1.28