



C368 SOFTWARE RELEASE NOTES

1.71

C368 software update 1.71 is a maintenance release that includes the following changes:

- Improvements to the internet software upgrade process of the optional BluOS* module
- Fix issue of front panel display not completely turning off when "Temporary Display" option is set to "On"

** Applies to units with the optional MDC BluOS module installed*

Software Package

C368 MCU 1.71 VFD 1.22 software package includes the following software version details:

- Main : V1.71
- VFD : V1.22

It is not necessary to upgrade BT software as it remains the same.

- BT : V1.26