



# C388 SOFTWARE RELEASE NOTES

## MCU 1.74

---

C388 software update MCU 1.74 is a maintenance release that includes the following change:

- Firmware support for MDC USB DSD\*

\* *Applies to units with the optional MDC USB DSD module installed*

## Software Package

---

C388-MCU-1.74-VFD-1.22-BT-1.26 software package includes the following software version details:

- Main : V1.74
- VFD : V1.22\*\*
- BT : V1.26\*\*

\*\* *Check the current VFD and BT software versions of your C388. It may not be necessary to upgrade VFD and BT software as they remain the same from previous software update.*