



SERVICE BULLETIN

Product: M51

Service Bulletin Number: M51-SB2014-02

Date: 15 October 2014

Subject: Software upgrade to v1.50

Modification applicable for units prior to serial number:

Recommended for ☐ all units ☒ returned units for service/repair
 ☐ up to specified serial number ☐ others (*specify*)

DESCRIPTION

- Add "Auto Display" feature.*
- Resolve minor software bugs.

* Refer to updated owner's manual for the description of "Auto Display" feature.

SOLUTION

Update the unit with the upgrade file
M51_APP_V1.50.rar

UPGRADE PROCEDURE

Refer to TD 2012-02r2 (Software Upgrade Procedure - USB).