

CI 8-120 DSP SOFTWARE RELEASE NOTES

The following CI 8-120 DSP software version list outlines recent changes to the CI 8-120 DSP software. You must always update your CI 8-120 DSP so that it will be running the latest software version.

MCU 2.26

Date: 12 November 2021

 Add "Stop" detent for all gain/volume knobs to prevent accidental or instantaneous dragging of the knob from -6 to +6

MCU 2.25

Date: 23 August 2021

Add "Power Status/Mute Status/Output Gain" status command for IP codes

• Restore Input Gain range to -6 to +6

MCU 2.24

Date: 24 July 2021

• Change volume range in Test Signal setting to 0 – 100 with 0 starting at the bottom, 25 at 9 o' clock position and 50 at the top, etc.

MCU 2.23

Date: 14 May 2021

Improve "Load Preset" functionality

• Add Mute function for every Output Channel

MCU 2.22

Date: 7 April 2021

Fix issue of unit powering up via 12Vdc (High) Trigger at ECO setting



CI 8-120 DSP SOFTWARE RELEASE NOTES

MCU 2.21

Date: 24 February 2021

Change default values of the following

Low Pass (on right) 15000 Hz High Pass (on left) 100 Hz

• If there is no unit name, use the model number and last four MAC digits

MCU 2.20

Date: 10 December 2020

• Set default values of the following at DSP page

Low Pass 100 Hz
1st band 100 Hz
2nd band 300 Hz
3rd band 1000 Hz
4th band 12000 Hz
5th band 15000 Hz
High pass 15000 Hz

MCU 2.19

Date: 23 October 2020

• Improve IP Codes function

MCU 2.18

Date: 18 September 2020

Improve DSP Gain control knob functionality



CI 8-120 DSP SOFTWARE RELEASE NOTES

MCU 2.17

Date: 14 August 2020

 Scale User Interface (UI) window screen to properly fit into MacOS, Windows, iOS and Android devices

MCU 2.15

Date: 10 July 2020

Improve Input/Output/DSP/Test signal control functionality

MCU 2.14

Date: 7 July 2020

• Add ECO mode prompt function

Add Auto OTA function

MCU 2.12

Date: 24 August 2019

Fix issue of output volume not adjustable at Mono or Bridge mode

MCU 2.11

Date: 9 August 2019

Adding control command console to acquire standby time

MCU 2.10

Date: 8 August 2019

- Adjust the boot-up self-check time to 10 seconds LED lights will be red during self-check
- Synchronize channel voice output with channel LED output when booting.